G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400

Page 1 of 14 Ranch Style Home Inspection

Definitions

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Appears Serviceable We did not observe conditions that would lead us to believe problems existed with this system or component.

The item is capable of being used. Some serviceable items may, however, show wear and tear. Other

conditions if applicable, will be noted in the body of the report.

This item or component warrants additional attention, repair, or monitoring. Marginal

Repair Recommend further review and repairs as needed by a qualified licensed contractor or specialty tradesman

dealing with this item or system.

Safety Hazard This item is a safety hazard. Correction is needed.

Not Present Item not present or not found.

Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at Not Inspected

time of inspection.

General Information

Property Information

Property Address SAMPLE RANCH INSPECTION

City EDISON State NEW JERSEY Zip ZIP CODE

Contact Name REALTOR'S NAME Phone PHONE # Fax FAX NUMBER

Client Information

Client Name BUYER'S NAME

Client Address BUYER'S HOME ADDRESS

City EDISON State NEW JERSEY Zip 08820

Phone BUYER; S # Fax FAX NUMBER IF APPLICABLE

E-Mail BUYER'S E-MAIL ADRESS

Inspection Company

Inspector Name GERALD WARREN

Company Name G. Warren, Inc.

Company Address PO Box 4526

City Metuchen State NJ **Zip** 08840

Phone G WARREN INC HOME INSPECTION Fax 908-753-1711

E-Mail gwarreninc@aol.com

File Number 0801072206

Amount Received PAID IN FULL (CHECKS)

Conditions

Others Present Buyer's Agent Property Occupied (Occupied)

Estimated Age 40 YEARS Entrance Faces (Unknown)

Inspection Date 08-01-07

Start Time 1:45 PM End Time 4:30 PM

Electric On Yes

Gas/Oil On Yes

Water On Yes

Temperature 80 DEGREES

Weather Clear Soil Conditions Damp

Space Below Grade Basement

Building Type Ranch style Garage (Detached)

Sewage Disposal Determination, not included in inspection How Verified (not part of

inspection)

G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400 Page 2 of 14 Ranch Style Home Inspection

General Information (Continued)

Water Source Determination, not included in inspection How Verified (not part of inspection) Additions/Modifications (unknown, no documentation supplied)

Permits Obtained (Recommend permit search for repairs/alterations) How Verified permit search not included in inspection, recommend permit search for alterations/repairs or equipment replacement

Lots and Grounds

1. Appears Serviceable 2. Repair	Driveway: (concrete) general normal maintenance required Walks: (concrete) more than Normal settlement noted., general maintenance required, REPAIR NEEDED, Trip hazard, lifted slab or slabs by trees, recommend evaluation and repair by licensed
	contractor before closing
3. Appears Serviceable	Stairs/exterior/front: (One step entrance) general maintenance require,
	maintain and repair when necessary
4. Appears Serviceable	Rear/exterior/stairs: (One step entrance) general maintenance require,
	maintain and repair when necessary
Marginal	Grading: (Flat) Flat site could cause water problems in severe
	weather, Recommend adding soil to slope away from foundation at
	the flat areas as a precaution against exterior water pooling
	or interior water penetration.

6. Appears Serviceable Vegetation: (Shrubs)

7. Repair Walls/Retaining: (Brick) REPAIR NEEDED Wall is leaning

Exterior Surface and Components

major house covering Exterio	r Surface ————————————————————————————————————
,	Type: (Brick veneer) General maintenance required, maintain and
	repair when necessary
2. Appears Serviceable	Trim/Fascia: (Metal) General maintenance required, maintain and repair when necessary
3. Appears Serviceable	Soffits: (Metal) General maintenance required, maintain and repair when necessary
4 Danain	
4. Repair	Bell: (Standard) Inoperative, needs repair
5. Appears Serviceable	Doors/entry: (Exterior door, Conventional) Regular normal door maintenance needed, adjust hardware, door and check weather strip.
6. Appears Serviceable	Door/patio or deck: (side exterior door) normal general maintenance required on door, hardware, weather strip, etc. maintain and repair as necessary
7. Appears Serviceable	Window Wells: (Window wells noted) General maintenance required
8. Safety Hazard	Elect Outlets ext: (110 VAC) older screw cap type outlet, recommend up date for safety

G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400 Page 3 of 14 Ranch Style Home Inspection

Garage/Carport

Detached Ga	rage
-------------	------

1. Type of Structure: (Concrete walls) Car Spaces: one

2. Repair Door/vehicle: (roll up) General maintenance required, maintain and repair when necessary, REPAIR NEEDED, Damaged door panels,

repairs needed. - recommend evaluation and repair by licensed $% \left(1\right) =\left(1\right) \left(1\right) +\left(1\right) \left(1\right) \left(1\right) +\left(1\right) \left(1\right) \left($

contractor before closing

3. Appears Serviceable Operation/door: (Functional) General maintenance required, maintain

and repair when necessary the track wheels, track adjustments and mechanical adjustments

4. Appears Serviceable Opener/door: (Manual) General normal maintenance required

5. Appears Serviceable Ext. Surface: (Same as House)

6. Repair Roof: (Asphalt shingle) Roof at end of useful life, recommend

evaluation and repair by licensed contractor before closing

7. Appears Serviceable Structure/roof: (Standard Truss framing)

8. Repair Door/exterior: (solid wood) REPAIR NEEDED, Poor condition, repairs

needed, recommend evaluation and repair by licensed contractor $% \left(1\right) =\left(1\right) \left(1$

before closing

9. Appears Serviceable Ceiling: (Exposed framing)

10. Appears Serviceable Walls: (Concrete)

11. Appears Serviceable Floor/Foundation: (concrete floor)

12. Appears Serviceable Electrical: (110 V Standard)

13. Appears Serviceable Windows: (Standard windows) General maintenance required, caulk,

seal, free up and maintain and repair when necessary

14. Marginal Gutters/Downspouts: (Aluminum gutters/downspouts) general

maintenance required, caulk, seal,, clean and repair Note-en ground drains, termination not determined recommend above

ground extensions where necessary

15. Marginal Additional Observations: (Retaining wall) retaining wall and brick

work behind garage needs maintenance and repair

Structure

1. Appears Serviceable Structure Type: (Concrete and brick) foundation structural

settlement is average for age

2. Appears Serviceable Foundation: (Poured slab) foundation settlement is average for the

age of the dwelling

3. Appears Serviceable Beams: (Solid wood)

4. Appears Serviceable Walls: (Brick/mortar) the visible inspection of the structural

walls, appears serviceable, The structural walls are covered by finished material, no liability will be accepted for improper construction or problems covered by finished wall material.

5. Appears Serviceable Joists/Trusses: (conventional wood framing)

6. Appears Serviceable Columns: (Steel support columns)

7. Appears Serviceable Floor/Slab: (concrete floor) floor settlement is average for the

age of the dwelling

G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400

Page 4 of 14 Ranch Style Home Inspection

Roof

(Main roof) Roof Surface -

- 1. Method of Inspection: (Ground level)
- 2. Style Rroof: (Gable)
- 3. Repair

Material: (Asphalt Shingles) Roof settlement is average for the age of the dwelling, REPAIR NEEDED, deterioration/shingle damage roof shows signs of deterioration and shingle damage, recommend evaluation and repairs by licensed contractor before closing, Roof near end of useful life

- 4. Est./shingle layers: appears two layers Note the layers of shingle is estimated from a side view of the shingles at the edge of the roof, However, many times the shingle edge is covered with metal and not exposed. The inspector is not allowed to lift shingles to determine the exact number of shingle layers. MAINTENANCE NOTE - if there is two layers of shingle, more than normal maintenance is required on the roof and flashings due to the age of the old flashings.
- 5. Estimated Age: 16 to 18 years estimated age
- 6. Type Shingles: Standard shingles manufactures estimated useful life of shingles is 18 to 22 years with proper professional installation and maintenance
- 7. Appears Serviceable Flashing: (Flashing material not visible Regular flashing maintenance is required to avoid roof leaks.
- 8. Appears Serviceable Valleys: (not visible) Regular valley maintenance is required to
- avoid roof leaks. 9. Appears Serviceable Vents/plumbing: (not visible) General periodic vent pipe flashing
 - maintenance is recommended to avoid roof leaks, One has to go on roof to check or service flashings which is outside the scope of a home inspection
- 10. Appears Serviceable Gutters/Downspouts: (Aluminum) General normal maintenance required, maintain and repair when necessary

back side of house Chimney -

11. Appears Serviceable Chimney: (Brick and mortar) General maintenance of chimney and flashing is required to avoid water problems.

12. Repair

Flue/Flue Cap: (No flue liner noted) Chimney interior condition of flue liner and chimney caps are not visible and not included in inspection. The report that the flue "appears serviceable " means that there is a visible flue liner sticking out of the top of the chimney, the statement is not a opinion or quarantee of condition.

13. Repair

Flashing/chimney: (Unknown, not visible) General periodic chimney flashing maintenance is recommended to avoid roof leaks, One has to go on roof and lift shingles to inspect flashings which is outside the scope of a home inspection, REPAIR NEEDED, Flashing leak noted in attic

G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400 Page 5 of 14 Ranch Style Home Inspection

Electrical

- 1. Service Size Amps: (150 Amps estimated)) Volts: 110-240 VAC
- 2. Appears Serviceable Service: (overhead conventional utility line)
- 3. Appears Serviceable 120 VAC Branch Circuits: (Copper)
- 4. Appears Serviceable Conductor Type: (Non-metallic sheathed cable)

2. Appears Serviceable Ventilator: (Fan ventilator) vents to exterior

Dishwasher: (No dishwasher)

contractor before closing

16. Appears Serviceable HVAC Source: (Main heating sys.)

- 5. Appears Serviceable **Ground**: (grounding sys. not visible) the actual grounding line is not visible however, the system is grounded
- 6. Not Inspected Smoke Detectors: (Not part of inspection) Not inspected, normally the township will test smoke detectors

(Basement) Electric Panel -

- 7. Appears Serviceable Manufacturer: (Murray)
- 8. Maximum Capacity: (Panel capacity rating, not verified)
- 9. Appears Serviceable Main Breaker Size: (150 amps estimated)
- 10. Appears Serviceable Breakers: (Standard modern breaker)
- 11. Is the panel bonded? Yes

(First floor) Kitchen -

3. Not Present

Kitchen

1. Appears Serviceable Stove/oven: (Standard stove/oven) older stove, still functional,

General maintenance and cleaning of burners is recommended

	4. Air Gap Present? No	Distinction. (No distinct)
	•	Refrigerator: (Standard refrigerator) Any test of refrigerator is
	6. Appears Serviceable	courtesy only, no guarantees Sink: (Standard sink)
	7. Safety Hazard	Electrical: (Two prong outlets) old two prong outlets, recommend up
	8. Appears Serviceable	date to three prong and GFCI outlets for safety Plumbing/Fixtures: (Standard faucet/plumbing)
	9. Appears Serviceable	Counter Tops: (Standard counter top)
1	O. Marginal	Cabinets: (Older standard cabinets) older cabinets with noticeable
		wear and tear, cabinets are still functional but need adjustment and maintenance
1	1. Appears Serviceable	Ceiling: (Drywall) normal general maintenance required on all
		ceilings, paint, fill common cracks, maintain and repair when necessary
1	2. Appears Serviceable	Walls: (Drywall/tile) normal general maintenance required, fill
		common cracks, maintain and repair when necessary,
1	3. Appears Serviceable	Floor: (Tile) floor settlement is average for the age of the dwelling
1	1 Appears Corrigophic	
	4. Appears Serviceable	Doors: (Standard entry door) Normal door maintenance required, adjust doors, hardware and maintain.
1	5. Repair	Windows: (Wood double hung) General maintenance required, caulk,
		seal, free up and maintain and repair when necessary, REPAIR
		NEEDED, hard operation-needs maintenance and improvements for ease of operation, recommend evaluation and repair by licensed
		ease or operation, recommend evaluation and repair by incensed

(1st floor main) Bathroom

7. Marginal

G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400 Page 6 of 14 Ranch Style Home Inspection

Bathroom

(15t 11001 main) balliloom —	
1. Appears Serviceable	Doors: (standard wood door) Normal door maintenance required,
	adjust doors, hardware and maintain.
2. Safety Hazard	Electrical: (No electric outlet) No outlet noted, recommend
	installing outlet to meet modern day electrical demands, light
	plug in outlets are not considered functional bathroom outlets
3. Appears Serviceable	Cabinet/counter: (Standard cabinets)
4. Appears Serviceable	Sink/Basin: (Standard sink)
5. Appears Serviceable	Faucets/Traps: (Standard faucets/plumbing)
6. Appears Serviceable	Tub/Surround: (Tub/plastic surround) caulking maintenance - replace
	caulking and sealer at tub surround when necessary
7. Appears Serviceable	Toilets: (Standard toilet)
8.Marginal	Ventilation/heat: (Window vent) general maintenance required, window
	is stuck closed
9. Appears Serviceable	Additional Observations: (Basement toilet) bathroom toilet is

Living Space

functional, toilet is in open, not really a half bath

inspection. Any report or comment on the following is courtesy only,no guarantees given or liability accepted.

Floors - Floors covered by carpets, tiles, Pergo wood or other type coverings, cannot be judged for structure or condition. Floor damage and stains may also be hidden by furniture which restricts and limits the inspection.

Walls - The condition of walls behind wallpaper, paneling and furniture cannot be judged.

8. Appears Serviceable HVAC Source: (Main heating sys.)

all rooms except kitchen and	bathrooms Living Space ————————————————————————————————————
•	Closet: (Standard) general normal door maintenance required, adjust
	hardware and door when necessary
2. Appears Serviceable	Ceiling: (Drywall) normal general maintenance required, paint, fill
	common cracks, maintain and repair when necessary
3. Appears Serviceable	Walls: (Drywall) normal general maintenance required, fill common
	cracks, maintain and repair when necessary
4. Appears Serviceable	Floor: (wood) floor settlement is average for the age of the
	dwelling
5. Appears Serviceable	Doors: (Standard interior doors) Normal door maintenance required,
	adjust doors, hardware and maintain.
6.Marginal	Windows: (Wood double hung) General maintenance required, caulk,
	seal, free up and maintain and repair when necessary, older
	windows, all need maintenance or repair

Electrical: (Two prong outlets) old two prong outlets throughout house, recommend up date to three prong outlets for safety

G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400 Page 7 of 14 Ranch Style Home Inspection

Air Conditioning

(Split system/Central air) AC System -

1. Appears Serviceable A/C System Operation: (Functional) Recommend obtaining a service contract on A/C compressor/condenser and system, and have the unit/system checked and serviced periodically as per the manufactures recommendation.

NOTE - The adequacy of the central air unit is beyond the scope of a home inspection. The inspector is not required to determine cooling supply adequacy or distribution balance. The inspector will determine if the temperature differential between the supply and return air is within an acceptable range of a functional unit.

2. Appears Serviceable Condensate Removal: (PVC) limited view of Condensate line, not leaking at time of inspection, however a Condensate line needs periodic inspection for leaks. leaks from this type line that goes unnoticed has been known to do serious rust damage to the furnace

- 3. Appears Serviceable Exterior Unit: (Ground level mount)
- 4. Unable To Inspect: (not applicable)
- 5. Manufacturer: Carrier
- 6. Model Number: undetermined Serial Number: undetermined
- 7. Area Served: Complete dwelling Approximate Age: 6 years, estimated age
- 8. Appears Serviceable Supply Temperature 55 degrees adequate temperature differential Return Temperature (68 degrees return temperature)
- 9. Fuel Type: 120-240 VAC Temperature Differential: acceptable temp range
- 10. Type: Central A/C Capacity: (Not verified)
- 11. Appears Serviceable compressor/condenser: (standard) normal periodic maintenance required as per manufactures recommendations, recommend obtaining a service contract before closing
- 12. Appears Serviceable Refrigerant Lines: (Serviceable condition)
- 13. Appears Serviceable Electrical Disconnect: (Standard electrical box) electrical disconnect visible inspection only, the disconnect is not tested with a standard home inspection
- 14. Appears Serviceable Ductwork: (Metal) limited view of ductwork, full finished dwelling
- 15. Appears Serviceable Blower Fan/Filters: (Fan/disposable filter Same fan and filter used for furnace and central a/c. See heating comments if any, on furnace blower fan and filter
- 16. Appears Serviceable Thermostats: (Standard) Thermostats are not checked for calibration or timed functions. The inspection is limited to whether or not the thermostat turns the heating unit on and off

G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400

Page 8 of 14 Ranch Style Home Inspection

Attic

71110		
main house section Attic —		
1. Method of Inspection: In	the attic	
2. Appears Serviceable	<pre>Framing/roof: (Standard Truss framing) Frame settlement is average for age</pre>	
3. Appears Serviceable	Sheathing: (standard sheathing)	
4. Repair	Ventilation: (Gable vents) attic needs venting improvement, soffit vents have been covered over with metal	
5. Not Inspected	<pre>Insulation: (unknown, not visible) attic completely floored, insulation if any, not visible</pre>	
6. Not Inspected	Depth/insulation: (Undetermined)	
7. Not Inspected	Vapor Barrier: (Not visible)	
8. Repair	Fan/attic: (home made fan setup) recommend roof vents be installed instead of hanging fan by gable vent.	
9. Appears Serviceable	Wiring/Lighting: (110 VAC)	
10. Appears Serviceable	Moisture: (none noted, limited view) Note - limited inspection of	
	attic, this is a visual inspection, moisture instrument testing is not part of the inspection, no liability will be accepted for	
	moisture content.	
11. Repair	Additional Observations: (Repair observation) soffit vents closed off, recommend up date of attic venting	
12. Safety Hazard	Additional Observations: Rail around stair opening in attic unsafe rails, openings in rails is too wide, child could crawl under	

Basement

and fall down the stair well

(Main house basement) Basement -

- 1. Basement type (Open basement) Observation/scope Note open basement disclaimer this is a visible inspection the inspector is not responsible for areas hidden by storage or finished areas. See moisture comments, A report of no water problems noted at the time of inspection, does not guarantee that there will never be water penetration into the basement. All basements are below ground and susceptible to water penetration particularly in severe weather.
- 2. Appears Serviceable Ceiling: (Ceiling tiles) normal general maintenance required on ceiling tiles
- 3. Appears Serviceable Walls: concrete and drywall Foundation settlement is average for age of dwelling
- 4. Safety Hazard Floor: (concrete) floor settlement is average for the age of the dwelling, also noted tile covered, believe the tiles may contain asbestos, recommend evaluation and repair by licensed contractor

before closing

- 5. Not Present Floor Drain: (None noted)
- Windows: (Metal windows) Standard windows normal general 6. Repair maintenance required, caulk, seal, paint, repair where necessary. maintenance needed, rust on metal noted
- 7. Marginal Electrical: (Two prong outlets) recommend up date to three prong for
- 8. Not Present Sump Pump: (None noted, limited view, floor tile covered)
- 9. Appears Serviceable Moisture stains: (None noted)

G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400 Page 9 of 14 Ranch Style Home Inspection

Basement (Continued)

10. Safety Hazard

Basement Stairs/Railings: (Stairs/hand rail) Hand rail needed on right side of basement stairs. A person or child could fall off the stairs to basement floor without a safety rail.

Heating System

(Basement) Heating System -

1. Repair

Heating System Operation: (Functional needs service) Dirt in burn chamber and unusual flame pattern, it appears that the unit has not been serviced in the last year as per manufactures service requirements, recommend evaluation and repair by licensed contractor before closing

- 2. Manufacturer: Weil McLain
- 3. Type: Boiler system/hot water Capacity: 119000 btu
- 4. Area Served: Complete dwelling Approximate Age: 17 years, estimated age
- 5. Fuel Type: Natural gas
- 6. Unable to Inspect: (Furnace heat exchanger and internal sections)
- 7. Appears Serviceable Distribution: (Radiator/hot water)
- 8. Appears Serviceable Flue Pipe: (Metal flue pipe)
- 9. Appears Serviceable Controls: (Operational controls) Operational controls the only controls tested were the operation controls, manufactures safety controls were not tripped or tested, this is beyond the scope of

a home inspection

10. Appears Serviceable Thermostats: (Standard) Thermostats are not checked for calibration

or timed functions. The inspection is limited to whether or not the thermostat turns the heating unit on and off

- 11. Tank Location: N/A
- 12. Suspected Asbestos: No

Plumbing

 Appears 	Serviceable	Service	Line:	(Copper))
-----------------------------	-------------	---------	-------	----------	---

- 2. Appears Serviceable Water Shutoff: (Basement)
- 3. Appears Serviceable Water Lines: (Copper) limited view of water lines, no

responsibility or liability will be accepted for any plumbing

lines of any type that are not visible

4. Repair Drain Pipes: (Cast iron) limited view of drain and vent lines, no

responsibility will be accepted for any plumbing lines of any type that are not visible, REPAIR NEEDED, corrosion noted on

drain lines in the basement

5. Appears Serviceable Vent Pipes: (Standard vent lines) limited view of drain and vent

lines, no responsibility will be accepted for any plumbing lines

of any type that are not visible

6. Appears Serviceable Gas Service Lines: (black iron/Insulflex)

Basement Water Heater -

7. Repair Water Heater Operation: Functional at time of inspection Water heater

is past the end of it's design life, presently making noise

which is a sign that it needs replacement

8. Not Present Water Catch Pan: (None noted) recommend installing a catch pan and

Palm-Tech Inspector, Copyright © 1998-2006, PDmB, Inc.

G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400

Page 10 of 14 Ranch Style Home Inspection

Plumbing (Continued)

Water Catch Pan: (continued)

drain as a safety precaution in the event of a leak. A catch pan is recommended when the heater is located in a finished area or near a finished area.

- 9. Manufacturer: Rheem
- 10. Model Number: (undetermined) Serial Number: (undetermined)
- 11. Type: Natural gas Capacity: 40 Gal.
- 12. Approximate Age: 20 years, estimated age Area Served: Complete dwelling
- 13. Appears Serviceable Flue Pipe: (Metal flue pipe)
- 14. Appears Serviceable TPRV and Drain Tube: (Copper)

Laundry Room/Area

Basement Laundry Room/Area ————————————————————————————————————			
	Electrical: (Standard outlet)		
2. Appears Serviceable	<pre>Vent/dryer: (Metal flex)</pre>		
3. Appears Serviceable	Gas Line/dryer: (Standard utility line)		
4. Safety Hazard	Floor: (Tile) tiles may be asbestos tiles, evaluation by licensed		
	contractor is recommended before closing		
Repair	Drain/washer: Drains to laundry tub REPAIR NEEDED, leak at tub		
	drain		
6. Not Present	Catch Pan/washer: (None noted) recommend installing a catch pan and		
	drain as a safety precaution in the event of a leak. A catch pan		
	is recommended when the washer is located in a finished area or		
	near a finished area or stored items.		
7. Appears Serviceable	Washer/Dryer (Washer/Dryer) any test of washer and dryer is		
	courtesy only, no guarantees, washer is functional dryer not		
	tested not plugged into outlet. No extension cord available		

tested, not plugged into outlet, No extension cord available 8. Repair Additional Observations: (Maintenance or repair needed) home made shower stall, not tested, water shower head on wrong wall

G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400 Page 11 of 14 Ranch Style Home Inspection

Marginal Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Lots and Grounds

1. Grading: (Flat) Flat site could cause water problems in severe weather, Recommend adding soil to slope away from foundation at the flat areas as a precaution against exterior water pooling or interior water penetration.

Garage/Carport

- 2. Detached Garage Gutters/Downspouts: (Aluminum gutters/downspouts) general maintenance required, caulk, seal,, clean and repair Note-en ground drains, termination not determined recommend above ground extensions where necessary
- 3. Detached Garage Additional Observations: (Retaining wall) retaining wall and brick work behind garage needs maintenance and repair

Kitchen

4. (First floor) Kitchen Cabinets: (Older standard cabinets) older cabinets with noticeable wear and tear, cabinets are still functional but need adjustment and maintenance

Bathroom

5. (1st floor main) Bathroom Ventilation/heat: (Window vent) general maintenance required, window is stuck closed

Living Space

- 6. all rooms except kitchen and bathrooms Living Space Windows: (Wood double hung) General maintenance required, caulk, seal, free up and maintain and repair when necessary, older windows, all need maintenance or repair
- 7. all rooms except kitchen and bathrooms Living Space Electrical: (Two prong outlets) old two prong outlets throughout house, recommend up date to three prong outlets for safety

Basement

8. (Main house basement) Basement Electrical: (Two prong outlets) recommend up date to three prong for safety

G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400 Page 12 of 14 Ranch Style Home Inspection

Repair Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Lots and Grounds

- 1. Walks: (concrete) more than Normal settlement noted., general maintenance required, REPAIR NEEDED, Trip hazard, lifted slab or slabs by trees, recommend evaluation and repair by licensed contractor before closing
- 2. Walls/Retaining: (Brick) REPAIR NEEDED Wall is leaning

Exterior Surface and Components

3. Bell: (Standard) Inoperative, needs repair

Garage/Carport

- 4. Detached Garage Door/vehicle: (roll up) General maintenance required, maintain and repair when necessary, REPAIR NEEDED, Damaged door panels, repairs needed. recommend evaluation and repair by licensed contractor before closing
- 5. Detached Garage Roof: (Asphalt shingle) Roof at end of useful life, recommend evaluation and repair by licensed contractor before closing
- 6. Detached Garage Door/exterior: (solid wood) REPAIR NEEDED, Poor condition, repairs needed, recommend evaluation and repair by licensed contractor before closing

Roof

- 7. (Main roof) Roof Surface Material: (Asphalt Shingles) Roof settlement is average for the age of the dwelling, REPAIR NEEDED, deterioration/shingle damage roof shows signs of deterioration and shingle damage, recommend evaluation and repairs by licensed contractor before closing, Roof near end of useful life
- 8. back side of house Chimney Flue/Flue Cap: (No flue liner noted) Chimney interior condition of flue liner and chimney caps are not visible and not included in inspection. The report that the flue "appears serviceable " means that there is a visible flue liner sticking out of the top of the chimney, the statement is not a opinion or guarantee of condition.
- 9. back side of house Chimney Flashing/chimney: (Unknown, not visible) General periodic chimney flashing maintenance is recommended to avoid roof leaks, One has to go on roof and lift shingles to inspect flashings which is outside the scope of a home inspection, REPAIR NEEDED, Flashing leak noted in attic

Kitchen

10. (First floor) Kitchen Windows: (Wood double hung) General maintenance required, caulk, seal, free up and maintain and repair when necessary, REPAIR NEEDED, hard operation-needs maintenance and improvements for ease of operation, recommend evaluation and repair by licensed contractor before closing

Attic

- 11. main house section Attic Ventilation: (Gable vents) attic needs venting improvement, soffit vents have been covered over with metal
- 12. main house section Attic Fan/attic: (home made fan setup) recommend roof vents be installed instead of hanging fan by gable vent.
- 13. main house section Attic Additional Observations: (Repair observation) soffit vents closed off, recommend up date of attic venting

Basement

14. (Main house basement) Basement Windows: (Metal windows) Standard windows - normal general maintenance required, caulk, seal, paint, repair where necessary. maintenance needed, rust on metal noted

G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400 Page 13 of 14 Ranch Style Home Inspection

Repair Summary (Continued)

Heating System

15. (Basement) Heating System Heating System Operation: (Functional needs service) Dirt in burn chamber and unusual flame pattern, it appears that the unit has not been serviced in the last year as per manufactures service requirements, recommend evaluation and repair by licensed contractor before closing

Plumbing

- 16. Drain Pipes: (Cast iron) limited view of drain and vent lines, no responsibility will be accepted for any plumbing lines of any type that are not visible, REPAIR NEEDED, corrosion noted on drain lines in the basement
- 17. Basement Water Heater Water Heater Operation: Functional at time of inspection Water heater is past the end of it's design life, presently making noise which is a sign that it needs replacement

Laundry Room/Area

- 18. Basement Laundry Room/Area Drain/washer: Drains to laundry tub REPAIR NEEDED, leak at tub drain
- 19. Basement Laundry Room/Area Additional Observations: (Maintenance or repair needed) home made shower stall, not tested, water shower head on wrong wall

G. Warren, Inc.

PO Box 4526 Metuchen, NJ 08840 908-757-3400 Page 14 of 14 Ranch Style Home Inspection

Safety Hazard Summary

Exterior Surface and Components

1. Elect Outlets ext: (110 VAC) older screw cap type outlet, recommend up date for safety Kitchen

2. (First floor) Kitchen Electrical: (Two prong outlets) old two prong outlets, recommend up date to three prong and GFCI outlets for safety

Bathroom

3. (1st floor main) Bathroom Electrical: (No electric outlet) No outlet noted, recommend installing outlet to meet modern day electrical demands, light plug in outlets are not considered functional bathroom outlets

Attic

4. main house section Attic Additional Observations: Rail around stair opening in attic unsafe rails, openings in rails is too wide, child could crawl under and fall down the stair well

Basement

- 5. (Main house basement) Basement Floor: (concrete) floor settlement is average for the age of the dwelling, also noted tile covered, believe the tiles may contain asbestos, recommend evaluation and repair by licensed contractor before closing
- 6. (Main house basement) Basement Basement Stairs/Railings: (Stairs/hand rail) Hand rail needed on right side of basement stairs. A person or child could fall off the stairs to basement floor without a safety rail.

Laundry Room/Area

7. Basement Laundry Room/Area Floor: (Tile) tiles may be asbestos tiles, evaluation by licensed contractor is recommended before closing